







REPORT

The following is a summary of what has to be rectified after the last environmental inspection(23 JULY 2020):

IDENTIFIED ISSUES	PICTURE OF ISSUES	PICTURE OF RECTIFIED ISSUE	COMMENT
Uncovered Toxic waste		NONE	WE HAVE RECEIVED A REPORT FROM DEPARTMENT OF WASTE MANAGEMENT (STELLENBOSCH MUN). WE ARE IN CONTACT WITH AVERDA & WASTEMART ABOUT THE DISPOSAL. A METHOD STATEMENT WILL BE COMUNICATED WITH YOU BEFORE THE PROCESS STARTS.

<p>DRAINAGE HOLES IN DRIP TRAYS TO BE SEALED/CLOSED.</p>		<p>NONE</p>	<p>I WILL RECTIFY AND WE WILL CLOSE THE HOLES WHEN THE TRAYS ARE IN USE.</p>
<p>CLEANING OF TRUMALI ROAD</p>			<p>WE WILL KEEP ON MONITORING THE CLEANING AS YOU CAN SEE ON THE PICTURE.</p>
<p>DEMARCATATION OF WORKS-AREA</p>			<p>I WILL BE GETTING MORE NETTING THIS WEEK & I WILL SEND YOU MORE PICTURES WHEN I HAVE DEMARCATED THE SITE.</p>